



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

### Minerals Regulatory Program

May 11, 2007

Supervisor ADZ

**Mine Name:** Redmond Limestone Quarry

**Operator Name:** Western Clay Company

**Permit number:** M/041/004

**Inspection Date:** August 03, 2006

**Time:** 9:30 am

**Inspector(s):** Lynn Kunzler, DOGM

**Other Participants:** Jerome Bown, Matt Bown

**Mine Status:** Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

### Purpose of Inspection:

Routine inspection made while in the area.

### Inspection Summary:

Recent activity was noted at this site while driving down the highway. Inspection of the site showed that a screen plant and loader were on site. Operator has been removing some of the past mined material. All activity was within the permitted and disturbed area. There were no signs of erosion, trash or deleterious materials observed during this inspection.

### Conclusions and Recommendations:

No non-compliance issues were noted during this inspection.

Continue to monitor this site when in the area.

**Inspector's Signature** [Signature]

LK:pb

O:\M039-Sanpete\S0390018-Antelope\inspections\Insp-08302006.doc